


## MAX LOOSE

PULL THE LOOSE END ALL THE WAY THROUGH METAL ADJUSTMENT BUCKLE



MOVE THE ADJUSTMENT BUCKLE TOWARDS THE PLASTIC CLIP



MAX LOOSE SETTING



## MAX TIGHT

MOVE THE METAL ADJUSTMENT BUCKLE  
TOWARDS THE PLASTIC BUCKLE

PULL

HOLD



PULL THE WEBBING  
THROUGH THE METAL  
ADJUSTMENT BUCKLE



MAX TIGHT SETTING

